




B-525-14
16-14ga. 1/4 stud



25

B-539-10
16-14ga. #10 stud



25

B-523-06
16-14ga. #6 stud



25

B-527-10
16-14ga. #10 stud



25

B-589
16-14ga. .156 dia. tab



25

B-572
16-14ga. Female Quick Disconnect



25

MCT-5
16-14ga. Male Quick Disconnect



25

CB-646
12-10ga. to 16-14ga.




15

BSN-331
16-14ga.




25

BLT-B
16-14ga. .156 dia. tab




6

C-501-12
12-10ga. 1/2 stud



15

C-530-14
12-10ga. 1/4 stud



15

C-540-38
12-10ga. 3/8 stud



15

CSN-346
12-10ga.



15

C-528-10
12-10ga. #10 stud




15

D-350-14
8ga. 1/4 stud




10

D-352-12
8ga. 1/2 stud




10

E-358-12
6ga. 1/2 stud




10

F-366-38
4ga. 3/8 stud



10

F-366-56
4ga. 5/16 stud



15