


B-572
 16-14ga. Female
 Quick Disconnect




25

MCT-5
 16-14ga. Male
 Quick Disconnect




25

B-519-08
 16-14ga. #8 stud




25

B-527-10
 16-14ga. #10 stud



25

B-524-06
 16-14ga. #6 stud



25

B-518-38
 16-14ga. 3/8 stud




25

B-525-14
 16-14ga. 1/4 stud




25

B-539-10
 16-14ga. #10 stud



25

B-523-06
 16-14ga. #6 stud




25

BSN-331
 16-14ga.



25

C-530-56
 12-10 ga. 5/16 stud




12

C-530-14
 12-10ga. 1/4 stud




12

C-541-10
 12-10ga. #10 stud



12

C-528-10
 12-10ga. #10 stud



12

CSN-346
 12-10ga.




12

C-540-38
 12-10ga. 3/8 stud



12

CB-646
 12-10ga. to 16-14ga.




10

BLT-B
 16-14ga. .156 dia. tab




6

B-589
 16-14ga. .156 dia. tab



25

PR-10
 Joins 2 - .156 dia. Snap Plugs



6