

High Temperature Terminal Kit - Small

Part #: HTT-KIT-SM

Total Pieces: 495

Box: SMB-20

Small Metal Box
13-3/8"W x 9-1/4"L x 2"H

BACK				
AS-20-06 22-18 ga. #6 stud Non-Insulated High Temp Ring Terminals Qty. 30	BS-23-06 16-14 ga. #6 stud Non-Insulated High Temp Ring Terminals Qty. 30	CS-28-08 12-10 ga. #8 stud Non-Insulated High Temp Ring Terminals Qty. 20	D-350-14HT 8 ga. 1/4 stud Non-Insulated High Temp Ring Terminals Qty. 15	B-171-HT 16-14 ga. .187" tab Non Insulated High Temp Female Quick Disconnects Qty. 30
AS-33-10 22-18 ga. #10 stud Non-Insulated High Temp Ring Terminals Qty. 30	BS-37-10 16-14 ga. #10 stud Non-Insulated High Temp Ring Terminals Qty. 30	CS-28-10 12-10 ga. #10 stud Non-Insulated High Temp Ring Terminals Qty. 20	E-357-38HT 6 ga. 3/8 stud Non-Insulated High Temp Ring Terminals Qty. 10	B-172-HT 16-14 ga. .250" tab Non-Insulated High Temp Female Quick Disconnects Qty. 30
AS-22-14 22-18 ga. 1/4" stud Non-Insulated High Temp Ring Terminals Qty. 30	BS-25-14 16-14 ga. 1/4" stud Non-Insulated High Temp Ring Terminals Qty. 30	CS-30-14 12-10 ga. 1/4" stud Non-Insulated High Temp Ring Terminals Qty. 20	B-175-HT 16-14 ga. .250" tab Non-Insulated High Temp Female Flag Quick Disconnects Qty. 30	MCT-1-HT 16-14 ga. .250" tab Non Insulated High Temp Male Quick Disconnects Qty. 30
AS-45 22-18 ga. Non-Insulated High Temp Butt Connectors Qty. 30	BS-31 16-14 ga. Non-Insulated High Temp Butt Connectors Qty. 30	CS-46 12-10 ga. Non-Insulated High Temp Butt Connectors Qty. 20	HI-1 Min: 2 to 4 - 18 ga. Max: 1 - 16 ga. & 1 - 14 ga. High Temp Porcelain Wire Nut Connectors Qty. 15	HI-5 Min: 2 to 4 - 18 ga. Max: 2 - 18 ga. & 1 - 14 ga. High Temp Porcelain Wire Nut Connectors Qty. 15
FRONT				